ERRATA for

PE Electrical and Computer: Computer Engineering Practice Exam

Revisions are shown in red.

Question 128, p. 24:

Question 128 should read as follows:

A real-time kernel is considered a "bare bones" real-time operating system. At a minimum, a real-time kernel should provide:

(A)   task management, file management, memory management

(B)   task scheduling, task dispatching, file management

(C)   intertask communication, task dispatching, memory allocation

(D)   task scheduling, task dispatching, intertask communication

Question 540, p. 61:

The first sentence of Question 540 should read as follows:

Consider the single data byte $(AA)_{16}$ transmitted MSB first using standard EIA RS-232C levels in the following signal diagram (assume a single stop bit is used):